



DATE 05/01/08

Recall Notice

Sierra International is issuing an ***Immediate Recall*** on the 18-7718 Fuel Filter. This product is not manufactured to Sierra's material specifications and must be returned to Sierra International. Every attempt should be made to remove all product received before May 1st, 2008 from all distributor and dealer inventories. Product previously installed and functioning in the field does not need to be collected.

Our records indicate that you have received a select quantity of the above mentioned products, please contact our Technical Service Dept. at 877-ONE-TFXM (663-8396) to obtain a Return Goods Authorization number. An offsetting credit will be issued for the recalled products upon receipt. Replacement inventory will be available for shipment June 2, 2008. Please contact our Customer Service Dept. at 877-ONE-TFXM (663-8396) to reorder.

We apologize for the inconvenience incurred due to this recall. If you have any questions, please contact our Technical Service Dept. or your Teleflex Sales Professional. Please visit our web-site at www.teleflexmarine.com.

Sincerely,

A handwritten signature in black ink, appearing to read "Larry Louvier", with a stylized flourish at the end.

Larry Louvier
Product Manager – Engine and Drive Parts